


**Which transformer suitable for MR16 to run AC synchronous color changing ?**

## Transformer



**Output: AC12V**




**stable AC signal**

**OK**

## Electronic transformer (for Halogen lamp)



**Output: only 8~9V**



**unstable signal**

**NO**